


# LC 80



Manufacturer: LIEBHERR VERZAHNTECHNIK GMBH

Machine type: LC 80

Serial number: FN 0585

# LIEBHERR

1

2

3

4



5

6

## 1.0 Packing

The machine/equipment will be shipped either packed or unpacked depending on the contractual agreements. The transport route is also decisive for the type of packaging used. Unless otherwise agreed, the type of packaging will comply with the packaging instructions HPE specified by the Federal Association for Wood Packaging Means, Pallets, Export Packing (Bundesverband Holzmittel, Paletten, Exportverpackungen e.V.) and the Federal Association of Mechanical Engineering Establishments (Verein Deutscher Maschinenbauanstalten). The signs and notes marked on the packing must always be observed.

### Explanation of Signs



## Scope of Disassembly Work


The scope of disassembly work depends on the type and size of machine and equipment, the transport conditions, the local situation and the lifting equipment available.

**Care / Handling**

LIEBHERR HIGH-PERFORMANCE GEAR CUTTING MACHINES are high-precision machines and must be handled with utmost care during transportation. Shocks and vibrations affect the precision of the machines and must be avoided.

2  
3  
4  
5  
6

### Handling Information

 <b>DANGER</b>
<p><b>Never step beneath suspended loads!</b></p> <p><b>Use faultless ropes and chains only!</b></p> <p><b>Observe load-bearing capacity of the crane! Observe weight information in the shipping documents!</b></p>

Suspend machine or components only as shown in the illustrations and handle with care.

### Handling Equipment

In order to transport the machine, the following equipment is supplied free of charge:

- 1 lifting beam or cross beam
- 2 or 4 lifting eyebolts

<b>NOTE</b>
<p><b>Part of this equipment is supplied on a loan basis and must be returned to Liebherr after completion of the transportation work!</b></p> <p><b>Please use the enclosed shipping bill!</b></p>

### Damage in Transit

Damages in transit must be reported to the carrier or to Liebherr Verzahntechnik in writing immediately!

**Intermediate Storage**

If the machine/equipment is not installed and assembled immediately upon delivery, it must be stored in a protected area and covered suitably to keep it free from dust and moisture, especially when in unpacked condition. Outdoor storage without approved special protective packing is prohibited.

2

3

4

5

6

## Installation

Normally the machine/equipment will be transported to and installed on a suitably prepared site.

### Site Conditions

The shop floor must have **sufficient bearing capacity**.

Make sure that the surface the machine is installed on is free of unevenness.

Ensure free access to the control cabinet.

All units on the machine must be accessible.

Ensure sufficient **freedom of movement** for operators and maintenance personnel.

Provide for good **light conditions** on the site.

The type of installation and attachment used is shown on the layout plan of these operating instructions. Floating installation on vibration-damping levelling elements is well-proved. However, the machine may also be attached to the floor by means of tie bolts or dowel bolts.

If fasteners are included in the scope of delivery, please see installation instructions following the layout plan.

### 1.1 Transportation of a gear cutting machine with external automation

The transportation instruction applies to the following machines:

Module type (BK) 1 (LC 80 - LC 180)

Module type (BK) 2 (LC 200 - 380 resp. LCS 180 - 300)

Transportation equipment

We provide you the following transportation equipments depending on machine type at delivery of the machine:

- Transportation seesaws with chains




Fig. 1 BK1 und BK 2




Fig. 2 only BK 1

- 4 Rope screws



Fig. 3 Rope screws

2  
3  
4  
5  
6

## Transportation of the machine

### 1.1 Transportation of a gear cutting machine with external automation

#### NOTE

The transportation equipment is only a loan.  
It must be returned after completion of the transportation work to the following address:  
**LIEBHERR Verzahntechnik GmbH**  
Kaufbeurer Str. 141  
D-87437 Kempten (Allgäu)  
Abt. Versand

#### Damages during Transit

Damages in transit notifying the forwarding agent or the contact person at Liebherr Verzahntechnik immediately.

#### General Notes

You can the respective machine type (LC ...) gather from the delivering papers or the description on the machine.

It has to be taken care at the transportation that all transport locks are attached (red painted).

#### NOTE

The belt eyes attached at the machine bed at the side (see figure 4) aren't designed for raising the machine!

They only for the protecting of the machine on the truck.

Belt eyes




Fig. 4 Belt eyes

Depending on equipment and type of the machine we suggested different transportation-proceeded or transportation equipments.

**Gear cutting machine (BK1 and BK2) with external automation (Variant 1)**

At these machines the automation (conveyor etc.) is provided and is transported separately.

The control cabinet is fastened to the machine bed with a transport lock and is put at the on putting place onto the ground.

**Gear cutting machine (BK1 and BK2) with external automation (Variant 2)**

At these machines the automation (conveyor etc.) is provided and is transported separately.

The control cabinet gets up on supports connectedly to the machine bed and remains at the on putting place on this.

1.1 Transportation of a gear cutting machine with external automation

**Gear cutting machine  
(BK1 and BK2) with  
external automation  
(Variant 1)**

The roof and side shields of the machine housing are disassembled.  
Mount the 4 rope screws into machine bed in the appropriate places.




Fig. 5

The chains and fastening bolts of the enclosed transportation device are already adjusted correctly in most cases.




Fig. 6 Transport seesaws

Appending the transportation device to a crane with sufficient load bearing capacity.

**! DANGER**

**Make sure that the transportation device is fastened to the crane tightly!**

**Make sure that the rope screws are screwed tightly in machine bed!**

**Make sure that the chain hooks are tightly sit in the rope screws and the chain hook protection is closed!**

**Make sure that the length of the chains are so adjusted that the machine hangs horizontally!**

**Make sure that the chains do not touch the machine or parts of the machine!**

**Never stand at the transportation under the machine!**

**The load bearing capacity of the crane has to be taken into account!**


**Weight of the machines:**

**BK1 up to 12000 kg**  
**BK2 up to 18000 kg**  
**The exact weight you find in the so-called "packing list"!**

Transporting the machine to the desired place.

If the machine is placed on a oil collecting plate (optionally) this must be put correctly before the machine is sit down.

In rule the machine is put on so-called "leveling elements" which must be fastened to the bottom of the machine bed.



leveling elements

Fig. 7

1.1 Transportation of a gear cutting machine with external automation

**! DANGER**

Work at or under the raised, unsecured machine (suspended load) is forbidden!

Is work under the lifted machine inevitably, like e. g. the assembly of the leveling out elements then security procedures must taken. The machine must be protected with eloquently high under laying woods (hardwood) or steel blocks.

Now the control cabinet must be dismantled and put onto the ground:

**! DANGER**

The control cabinet must be fastened to the crane before the transport locks dismantled !

Mount the transportation eyes at the control cabinet and fastening the chains on it.

Observe the load-carrying capacity of the crane

Weight of the control cabinet: 1000 kg

Stretching the chains with the crane.

Making sure that the control cabinet doesn't fall when solving the transport locks.




Fig. 8

Transportation locks at the floor of the control cabinet.




Fig. 9

**NOTE**

The connection wires must be paid attention that at transporting of the control cabinet these aren't broken off!

1.1 Transportation of a gear cutting machine with external automation

Control cabinet sit beside the machine BK1 and BK2




Fig. 10

**Gear cutting machine  
(BK1 and BK2) with  
external automation  
(Variant 2)**

The roof and side shields of the machine housing are disassembled.  
Mount the 4 rope screws into machine bed in the appropriate places.




Fig. 11

The chains and fastening bolts of the enclosed transportation device are already adjusted correctly in most cases.




Fig. 12

## 1.1 Transportation of a gear cutting machine with external automation

Appending the transportation device to a crane with sufficient load bearing capacity.

**⚠ DANGER**

**Make sure that the transportation device is fastened to the crane tightly!**

**Make sure that the rope screws are screwed tightly in machine bed!**

**Make sure that the chain hooks are tightly sit in the rope screws and the chain hook protection is closed!**

**Make sure that the length of the chains are so adjusted that the machine hangs horizontally!**

**Make sure that the chains do not touch the machine or parts of the machine!**

**Never stand at the transportation under the machine!**


**The load bearing capacity of the crane has to be taken into account!**

**Weight of the machines:**  
BK1 up to 12000 kg  
BK2 up to 18000 kg  
**The exact weight you find in the so-called "packing list"!**


Transporting the machine to the desired place.

If the machine is placed on a oil collecting plate (optionally) this must be put correctly before the machine is sit down.

In rule the machine is put on so-called "leveling elements" which must be fastened to the bottom of the machine bed.



leveling element

 **DANGER**

Work at or under the raised, unsecured machine (suspended load) is forbidden!

Is work under the lifted machine inevitably, like e. g. the assembly of the leveling out elements then security procedures must taken. The machine must be protected with eloquently high under laying woods (hardwood) or steel blocks.

2

3

4

5

6

Control cabinet is mounted on the machine bed BK 1 and BK2
















Fig. 13

## 1.2 Layout and foundation plan

	Operating station
	Location of main power supply
	Connection for coolant fluid Center in flow direction
	Junction for compressed air
E	Electric cabinet
H	Hydraulic unit
S	Lubrication unit
C	Recooling unit
	Required space
	Directional symbol
	Attention voltage
	Anchor bolt
	Levelling screw
CH	Chip conveyor
D	Oil mist separator
K	Chip retainer
T	Transformer
OKF	Upper edge base
UKM	Lower edge machine
B 	Loading height
E 	Unloading height





tlak vzduchu  
 compressed air  
 DN 18  
 4 - 6 bar  
 500 - 800 l/min

7

6


5

4

3




2

pohled na stranu obsluhy bez skřínového rozvaděče  
view on operation side without control cabinet



4655


3167



A-A

merítko 1:5  
scale

hmotnosť s  
machine



celková prípojná hodnota: 38kVA  
 total connected load

F.-NR.:  
 výrobní číslo  
 serial number

0585, 0586

c	Tschechische Texte anstatt deutsche Texte			30.04.08	MITO
b	Gesamtanschlusswert geändert			22.06.07	HOCO
a	Kuehlaggregat versetzt, Hauptschaltergehaeuse hinzu			22.06.07	HOCO
AENDERUNGEN MODIFICATIONS				DATUM DATE	NAME NAME
MASSTAB SCALE	GEZ. DRAWN	15.02.07	Hoerner	WERKSTOFF MATERIAL	NORM STD
1:20	GEPR. CHECKED	30.04.08	Miller	ROHMASSE ROUGH DIM	
BENENNUNG DESCRIPTION				ZEICHNUNGSNUMMER DRAWING NUMBER	
AUFSTELLPLAN LC 80 MONTĀZNI VYKRES - INSTALLATION PLAN				56 02 806 02	
<b>LIEBHERR</b> Verzahrntechnik GmbH				BLATT SHEET	1 VON 1 OF 1
				ENTSTANDEN AUS RESULTED FROM	FORMAT FORMAT
ALLGEMEINTOLERANZ GENERAL TOLERANCE		UNBEMASSTE KANTEN UNDIMENSIONED EDGES		560272802	
ISO 2768 - M		x 45° GEBROCHEN CHAMFERED			

ABWICHLUNG GESTATTET

THIS DRAWING MAY NOT BE COPIED OR DISCLOSED TO THIRD PARTIES WITHOUT OUR PERMISSION  
 2006-04-24 ME10

## 2.0 Technical Data of Machine

<b>Hobbing machine</b>		<b>LC 80</b>
	Max. workpiece diameter	80 mm
	Table diameter	125 mm
	Max. table speed	800 1/min
	Center distance	10 ... 200 mm
	Total weight approx.	9500 kg
	Ambient temperature	12 ...38°C
	Relative air humidity	90% max. at 20°C 50% max. at 40°C
<b>Machine column</b>		
	Max. axial travel	250 mm
<b>Cutter head swivelling device</b>		
	Cutter head swivelling angle	+/- 45 degrees
<b>Cutter head</b>		
	Power	23 kW
	Max. module	3 mm
	Max. cutter speed	6000 1/min
	Max. cutter diameter	90 mm
	Max. cutter length	200 mm
	Max. tangential travel	180 mm
	Max. tangential speed	7500 mm/min
	Smallest teeth number to be cut	4

## Technical Data

## 2.0 Technical Data of Machine

<b>Operating and control voltage</b>		
	Operating voltage (tolerance +/- 10%)	400 V
	Operating frequency (tolerance +/- 2%)	50 Hz
	Control voltage	24 V DC
<b>Hydraulics</b>		
	Hydraulic oil	HLP 46
	Max. operating pressure	70 bar
	Pump delivery	24 l/min
<b>Wet-cutting device</b>		
	Max. average noise level	80 dB(A)
<b>Coolant system; Cooling oil</b>		
	Coolant quantity in machine bed	280 l
	Flow at nozzle max.	100 l/min
<b>Tailstock</b>		
	Max. travel of tailstock	300 mm
	Max. speed of tailstock	17000 mm/min

## 2.1 Calculating the Table Speed

During workpiece machining the controller calculates the appropriate table speed depending on the number of starts of tool and the number of teeth on the workpiece. If the maximum table speed is exceeded, an error message is displayed on the screen of the control panel.

In order to avoid exceeding the maximum permissible speed of the work-table (see Technical Data), the table speed may be calculated based on the following formulas.

You may calculate the current table speed using the following formula:


$n_t$  = table speed

$n_f$  = spindle speed

$Z_0$  = number of starts of tool

$Z_2$  = number of teeth on workpiece

$$n_t = \frac{z_0 \cdot n_f}{z_2}$$



With the EGB closed, ADDITIONNAL ROTARY MOTION may occur and influence the above calculated table speed.


## Technical Data

## 2.1 Calculating the Table Speed

We distinguish two additional movements:


Tangential-differential portion, caused by the V1-axis motion

$$n_t = \frac{z_0 \cdot n_f}{z_2} \pm \frac{2 \cdot z_0 \cdot v_V}{P_{z0} \cdot z_2}$$



Axial-differential portion, caused by the Z1-axis motion

$$n_t = \frac{z_0 \cdot n_f}{z_2} \pm \frac{2 \cdot \sin \beta_2 \cdot v_z}{z_2 \cdot m_n \cdot \pi}$$



Both portions may have a SUBTRACTING or an ADDING effect on the table speed depending on the direction of traverse.

If during machining both portions occur simultaneously, you may use the following formula to calculate the total table speed:


$$n_t = \frac{z_0 \cdot n_f}{z_2} \pm \frac{2 \cdot \sin \beta_2 \cdot v_z}{z_2 \cdot m_n \cdot \pi} \pm \frac{2 \cdot z_0 \cdot v_V}{P_{z0} \cdot z_2}$$

- $\beta_2$  = helix angle on workpiece in degrees
- $m_n$  = normal module in mm
- $z_0$  = lead on tool in mm
- $v_V$  = max. speed of V-axis in mm/mm
- $v_z$  = max. speed of Z-axis in mm/mm

### 3.0 Axis LC

#### Identification of the axes

The machine axes are identified by defined names which are a combination of a letter and an index number.



---

**Description of the machine****3.0 Axis**

<b>Standard axes</b>	Every hobbing machine is provided with the following axes:
<b>Linear axis</b>	X1-axis: radial axis of cutting head Z1-axis: axial axis of the cutting head V1-axis: tangential axis: tool
<b>Rotary axis</b>	B1-axis: tool axis - main drive C2-axis: workpiece axis
<b>Optional axis</b>	These axes depend on the machine design and type.
<b>Linear axis</b>	Z4-axis: motion of tailstock arm Z5-axis: workpiece-pocket-lowering Z6-axis: NC-lifting station (workpiece transfer ring loader-conveyor) Z7-axis: NC-lifting station (centrifugal station)
<b>Rotary axis</b>	C3-axis: ring loader rotary motion
<b>Cutter head swivel axis</b>	A1-axis: swivelling of cutter head